PRE-BID AUDITS

Facility	Steel Items to be Fabricated	MFSQA Form Submittal Date	Self Audit Result	Audit Request Date	Site Visit Date	Final Audit Results	Date Complete
Nippon Steel/Tokyo Rope, Japan China Railway Shanhaiguan Bridge Group, China China Railway Turnout Bridge - Boaji China Railway Turnout Bridge - Anqing Hochang Machinery Ind., South Korea Wire Rope Corp. of America, St. Joseph, MO. Wire Rope Corp. of America, Chillicothe, MO. Wire Rope Corp. of America, Cuatitlan, Mexico Zhenhua Port Machinery Co., China Shanghai Heavy Machinery Plant, China IHI-MHI, AICHI facility (IHI), Japan IHI-MHI, Yokohama facility (IHI), Japan IHI-MHI, Yokohama facility (MHI), Japan Japan Steel Works, Japan China Railway Turnout Bridge - Anshan	Wire, PPWS Wire, PPWS, Suspender Rope Tower, OBG Tower, OBG Tower, OBG Hinge K, Bearings, Shear Keys Wire rope, suspenders suspender wire suspender wire Tower, OBG Saddles Tower, OBG Tower, OBG Tower, OBG Tower, OBG Tower Saddle, East Saddle Saddles Saddles Saddles	11/23/05 12/13/05 12/13/05 12/23/05 12/23/05 12/30/05 01/10/06 01/10/06 01/10/06 02/14/06 02/10/06 02/10/06 02/10/06 02/10/06 02/10/06 02/10/06 03/09/06	Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved Approved	12/23/05 12/30/05 01/24/06 01/24/06 01/24/06 01/18/06 02/14/06	01/09/06 12/20/05 01/04/06 01/14/06 01/16/06 01/19/06 02/23/06 02/24/06 02/28/06 02/14/06 02/17/06 03/06/06 03/08/06 03/09/08 03/14/06 03/15/06	Pass Pass Incomplete Pass Contingent Pass Contingent Pass Pass Pass Pass Contingent Pass Incomplete Pass Pass Pass Contingent Pass Contingent Pass Pass Pass Pass Pass	01/23/06 03/06/06 03/06/06 03/06/06 02/17/06 02/20/06 03/07/06 03/10/06 03/17/06

Last updated on 3/17/06

Legend:

"Pass" Indicates that a facility currently appears to have all Facilities, Equipment, Personnel, and Procedures in place to conduct the work on the bid item indicated for this project.

"Fail" Indicates that a facility:

- a) Has not corrected all contingent items from a previous department audit for this project for the given bid item number, OR
- b) Appears to lack the ability to supply the bid item indicated within the parameters and/or schedule specified for this project.

"Contingent Pass"

Reasonable plans are in place to make necessary changes to the facility prior to the start of work on this project.

All contingencies must be corrected as determined by a passing department re-audit prior to fabrication to receive a status of "PASS."

For more detailed information regarding the results of the MFSQA and Department Audits please contact the audited facility directly. The Department will not release detailed results of audits to third parties.